#### DRAFT

# Appendix G

**Site Inspection Checklist** 

An annual site inspection of the Central Operable Unit (COU) was conducted on March 16, 2017 at the Rocky Flats site. This inspection consisted of a comprehensive walk-down of the entire COU looking for signs of erosion, subsidence, vegetation stress, debris, and any other environmental condition that could impact the remedy or associated engineered structures. The results of this annual inspection and site maps indicating the areas surveyed are provided following the FYR Site Inspection Checklist.

#### **Annual Site Inspection Team Roster**

Name	Title	Affiliation
Vera Moritz	RFLMA Project Coordinator	EPA Region 8
Carl Spreng	RFLMA Project Coordinator	CDPHE
Lindsay Masters	RFLMA Project Coordinator	CDPHE
Scott Surovchek	DOE-LM Site Manager	DOE-LM
Jeffrey Murl	DOE-LM Site Manager	DOE-LM

The Five-Year Review Site Inspection Checklist below was completed by reviewing site monitoring and inspection records for this FYR period and discussing checklist items with site staff.

# Five-Year Review Site Inspection Checklist Rocky Flats, Jefferson County, Colorado

I. SITE INF	ORMATION				
Site name: Rocky Flats, Central Operable Unit	Date of inspection: Various				
Location and Region: Jefferson County, Colorado	EPA ID: CO7890010526				
Agency, office, or company leading the five-year review: DOE-LM	Weather/temperature: Various				
Remedy Includes: (Check all that apply)    Landfill cover/containment					
Attachments: X Inspection team roster attached	□ Site map attached				
II. INTERVIEWS	(Check all that apply)				
1. O&M site manager Scale Successions Name Interviewed □ at site □ at office □ by phone Phone Problems, suggestions; □ Report attached	Title Date				
2. O&M staff  Name  Interviewed □ at site □ at office □ by phone Phone Problems, suggestions; □ Report attached	Title Date				

3.	Local regulatory authorities and response agencies (i.e., State and Tribal offices, emergency response office, police department, office of public health or environmental health, zoning office, recorder of deeds, or other city and county offices, etc.) Fill in all that apply.				
	Agency <u>EfA Lagran S</u> Contact <u>√E/A MAIT</u> Name  Problems; suggestions; □ Report attached		<i>V√ALIONS</i> Date	* 303-1/3-698 <sub>j</sub> Phone no.	
	Agency <u>CAPHE</u> Contact <u>CAPHE SPREARY</u> Name  Problems; suggestions; □ Report attached	Title	√ <u>ACJUUS</u> Date	383 × 692 - 3358 Phone no.	
	Agency CDPHE Contact LINDSAY MASTERS Name Problems; suggestions; □ Report attached		√40.1/2/.S Date	36 <u>3.693-33</u> 70 Phone no.	
	Agency Contact Name Problems; suggestions; □ Report attached	Title	Date	Phone no.	
4.	Other interviews (optional) □ Report atta	iched.			
<u> </u>	-14 contrador institut - gravistid signit for th	<u>LESS AND ING</u>	<u>.</u> 44. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4.		
44	undikin i net limite	COTECT COADMAR	1 aH2	gadiag. Wysichiaus	
<u> </u>	<u>is een hisaanar Patoigh i</u>		73/7/2	#####	

	III. ON-SITE DOCUMENTS &	RECORDS VERIFIED	(Check all that app	ly) ∦
<b>X</b> .	O&M Documents  ☑ O&M manual ☑ As-built drawings ☑ Maintenance logs Remarks Some O&M Anamaka	⊠ Readily available ⊠ Readily available ⊠ Readily available	□ Up to date □ Up to date □ Up to date □ Up to date	□ N/A □ N/A □ N/A
	-upatral an a samilt of	<u>aydan maliji</u> a	444	7
2.	Site-Specific Health and Safety Plan  M Contingency plan/emergency response  Remarks Site of State of the State of State	D25-44-4/4-3	e a Up to date	ONA ONA
3.	O&M and OSHA Training Records Remarks	⊮Readily available	<b>ビ</b> Up to date	□N/A
4.	Permits and Service Agreements  ☐ Air discharge permit ☐ Effluent discharge ☐ Waste disposal, POTW  ☐ Other permits ☐ Color of the col	□ Readily available	□ Up to date □ Up to date □ Up to date □ Up to date ⊠ Up to date	BIN/A BIN/A BIN/A DIN/A
5.	Gas Generation Records Remarks	□ Readily available	☐ Up to date	⊠ N/A
6.	Settlement Monument Records Remarks	ষ্টি Readily available	S"Up to date	O N/A
7.	Groundwater Monitoring Records Remarks Surface Cafee And And	BReadily available	≅Up to date	ON/A
8.	Leachate Extraction Records Remarks	□ Readily available	□ Up to date	₽ N/A
9.	Discharge Compliance Records  □ Air  □ Water (effluent)  Remarks Effluent (1226/224)	□ Readily available Readily available	□Up to date SaUp to date	ON/A ON/A
10.	Daily Access/Security Logs Remarks	□ Readily available	□ Up to date	&N/A

\* Documents discussed in this section are generally kept in LMS contracted officer, not on-8-44, unless they are required to be available on-8-44.

		IV. O&M COSTS	·········	
1.	O&M Organization  ☐ State in-house ☐ PRP in-house ☐ Federal Facility in-house ☐ Other	☐ Contractor for State ☐ Contractor for PRP ☐ Contractor for Federa	il Facility	
2.	O&M Cost Records  ☐ Readily available ☐ Up to ☐ Funding mechanism/agreement i Original O&M cost estimate  Total annual c	n place		
	From To Date From Date Date From Date Date	Total cost  Total cost  Total cost  Total cost  Total cost	☐ Breakdown attached	
3.	Unanticipated or Unusually High Describe costs and reasons:	1 O&M Costs During R		
	V. ACCESS AND INST	ITUTIONAL CONTRO	DLS &'Applicable □ N/.	<b>A</b>
A. Fen	cing			:
1.	Fencing damaged ☐ Locati Remarks	on shown on site map	☐ Gates secured	SVN/A
B. Oth	er Access Restrictions			
1,	Signs and other security measure Remarks	s		\

\* Son Soction 6.1.5 for discussion of of M cocts in this fourth

C.	Institutional Controls (ICs)	)					
***.	Implementation and earth Site conditions imply IC Site conditions imply IC	Cs not properly imple			Yes Yes	⊠No ⊠No	□N/A □N/A
	Type of monitoring (e.g Frequency <u>7/7257</u> Responsible party/agenc	6 2026 11949 CV 2008 - 1249		2 1/3/15			
	Contact <u>Soot Sa</u> Nam	wayshek		5778.498	A//j Dat		Phone no.
	Reporting is up-to-date Reports are verified by t	the lead agency			Yes Yes	□No □No	□N/A □N/A
	Specific requirements in Violations have been reported of the Problems or suggestions.	ported			Yes Yes	□No □No	□ N/A ₩N/A
2.	Adequacy Remarks FCs 4sc Estation was Est	\$1Cs are adequate		are inadequate		12	ON/A
D.	General		••••••				
1.	Vandalism/trespassing Remarks	☐ Location shown	on site map	⊠No vanda	lism e	vident	
2.	Land use changes on si Remarks	ite # N/A					
3.	Land use changes off si Remarks	ite\N/A			**************************************	***************************************	
		VI. GENERAL	SITE CONDIT	TIONS			
A.	Roads MApplicable	□ N/A	<i>i</i>		***************************************	***************************************	***************************************
1.	Roads damaged Remarks	☐ Location shown	on site map	≯Roads ade	rquate	□N/A	

	Remarks
	- Olusik sita degelation cover is grad.
	VIL LANDFILL COVERS WApplicable ON/A OLF 4 PLF *
. L	andfill Surface
Þ	Settlement (Low spots)
	Areal extent Depth  Remarks Inspections an general printically perfly Confell MAM Plans
	corresponding inspection checklists and aparts in who records and
·	Cracks GAN AS COURTS ☐ Location shown on site map ☐ Cracking not evident
	Lengths Widths Depths
	Remarks See Hampeles in VII A. I.
***************************************	Erosion □ Location shown on site map □ Erosion not evident
	Areal extent Depth  Remarks Social Accordance XII A. (
	Remarks 54 12224/12 4 1
,	Holes □ Location shown on site map Affoles not evident
	Areal extent Depth Remarks
	Notation No.
	Vegetative Cover  ☐ Grass ☐ Cover properly established ☐ No signs of stress
	Trees/Shrubs (indicate size and locations on a diagram)  Remarks <u>Magnifican coulds wood success estado Acaptia, assas tha</u>
	hist sierfly ben Sistastia
	Alternative Cover (armored rock, concrete, etc.)
	Remarks
	Bulges □ Location shown on site map □ Bulges not evident
	winges — Elocation shown on she map wildinges not evident
	Bulges ☐ Location shown on site map ☐ Bulges not evident  Areal extent Height  Remarks

\* The March 2017 OLF inspection sepert and the First Quarter (march 2017) PLF inspection seport as attached.

8.	Wet Areas/Water Damage ☐ Wet areas ☐ Ponding ☐ Seeps ☐ Soft subgrade Remarks	☐ Wet areas/water damage not ☐ Location shown on site map	evident Areal extent Areal extent Areal extent Areal extent Areal extent	
9.	Slope Instability ☐ Slides Areal extent Remarks <u>Se¢ Agarra</u>	□ Location shown on site map	☐ No evidence of slope instability	
В.	Benches	☐ N/A of earth placed across a steep lan of surface runoff and intercept ar	dfill side slope to interrupt the slope ad convey the runoff to a lined	
ì,	Flows Bypass Bench Remarks	☐ Location shown on site map	&rN/A or okay	
2.	Bench Breached Remarks	☐ Location shown on site map	≫N/A or okay	
3.		□ Location shown on site map	[X]N/A or okay	
C.	Letdown Channels Applicable (Channel lined with erosion contro slope of the cover and will allow the	l mats, riprap, grout bags, or gabi is runoff water collected by the b	ons that descend down the steep side enches to move off of the landfill	
1.	Settlement □ Locat Areal extent Remarks <u>See イルルルル</u>	Danth	evidence of settlement	rejort
2.	Material Degradation □ Locat Material type Remarks <u>S&amp; Asmaska</u>	ion shown on site map □ No Areal extent  A	evidence of degradation  **Tacked OLF Inopedion 14	part.
3.	Erosion Decat Areal extent Remarks <u>See again</u>	ion shown on site map Depth A. I sand all.	evidence of crosion	oest.

4,	Undercutting □ Location shown on site map □ No evidence of undercutting  Areal extent □ Depth  Remarks □ See summable in THE A I and Machel OLE inspection	14. p.c.
5.	Obstructions  U Location shown on site map  Size  Remarks 526 1211 such in VII A. Land Machael Oil inspection.	(Ly+0+1)
6.	Excessive Vegetative Growth  No evidence of excessive growth  Vegetation in channels does not obstruct flow  Areal extent  Remarks  Sociation shown on site map	ezyve e
D. Cov	ver Penetrations NApplicable ON/A	
smi.	Gas Vents  ☐ Active Passive ☐ Properly secured/locked ☐ Functioning ☐ Routinely sampled 反Good condition ☐ Evidence of leakage at penetration ☐ Needs Maintenance ☐ N/A Remarks	
2.	Gas Monitoring Probes  ☐ Properly secured/locked ☐ Functioning ☐ Routinely sampled ☐ Good condition ☐ Evidence of leakage at penetration ☐ Needs Maintenance 爲N/A Remarks	
3.	Monitoring Wells (within surface area of landfill)  □ Properly secured/locked □ Functioning □ Routinely sampled □ Good condition □ Evidence of leakage at penetration □ Needs Maintenance ② N/A  Remarks	
4.	Leachate Extraction Wells  ☐ Properly secured/locked ☐ Functioning ☐ Routinely sampled ☐ Good condition ☐ Evidence of leakage at penetration ☐ Needs Maintenance ②N/A  Remarks	
.5,	Settlement Monuments & Located & Routinely surveyed \( \subseteq \nabla N/A\) Remarks	

E.	Gas Collection and Treatment □ Applicable ☑ N/A	
1.	Gas Treatment Facilities  ☐ Flaring ☐ Thermal destruction ☐ Collection for reuse ☐ Good condition☐ Needs Maintenance Remarks	
2.	Gas Collection Wells, Manifolds and Piping  ☐ Good condition☐ Needs Maintenance  Remarks	
3.	Gas Monitoring Facilities (e.g., gas monitoring of adjacent homes or buildings)  □ Good condition□ Needs Maintenance □ N/A  Remarks  ———————————————————————————————————	
F.	Cover Drainage Layer □ Applicable ☒N/A	
1.	Outlet Pipes Inspected   Functioning   N/A  Remarks	
2.	Outlet Rock Inspected ☐ Functioning ☐ N/A Remarks	
G.	Detention/Sedimentation Ponds □ Applicable □ XN/A	
1.	Siltation Areal extent Depth □ N/A □ Siltation not evident Remarks	
2.	Erosion Areal extent Depth □ Erosion not evident Remarks	
3.	Outlet Works □ Functioning □ N/A  Remarks	
4.	Dam □ Functioning □ N/A Remarks	

H.	Retaining Walls	□Applicable	JY N/A	
1.	<b>Deformations</b> Horizontal displacement_ Rotational displacement_ Remarks	•	Vertical displac	☐ Deformation not evident ement
2.	<b>Degradation</b> Remarks	□ Location show	n on site map	☐ Degradation not evident
1. 1	erimeter Ditches/Off-Site-Di	eharge	<b>M</b> Applicable	□N/A
1.	Siltation	ion shown on site	map [] Siltation	
2.	Vegetative Growth  ☐ Vegetation does not imp Areal extent Remarks 5 / 2 / 1	oede flow		DN/A
3.				□ Erosion not evident
4,	Discharge Structure Remarks			
	VIII. VER	TICAL BARRII	R WALLS	] Applicable
1.	Settlement Areal extent Remarks	Depth		☐ Settlement not evident
2.	Performance Monitorin □ Performance not monito Frequency Head differential Remarks	red	D Evidence	

	IX. GROUNDWATER/SURFACE WATER REMEDIES	
A.	Groundwater Extraction Wells, Pumps, and Pipelines □ Applicable ☑N/A	
1.	Pumps, Wellhead Plumbing, and Electrical  ☐ Good condition☐ All required wells properly operating ☐ Needs Maintenance ☐ N/A  Remarks	
2.	Extraction System Pipelines, Valves, Valve Boxes, and Other Appurtenances  Good condition Needs Maintenance Remarks	AMMENTALIA
3.	Spare Parts and Equipment  ☐ Readily available ☐ Good condition☐ Requires upgrade ☐ Needs to be provided  Remarks	
В.	Surface Water Collection Structures, Pumps, and Pipelines   Applicable   N/A	
1.	Collection Structures, Pumps, and Electrical  ☐ Good condition☐ Needs Maintenance  Remarks	
2.	Surface Water Collection System Pipelines, Valves, Valve Boxes, and Other Appurtenances ☐ Good condition☐ Needs Maintenance Remarks	
3.	Spare Parts and Equipment  ☐ Readily available ☐ Good condition☐ Requires upgrade ☐ Needs to be provided  Remarks	

C.	Treatment System Applicable DN/A
Ĵ.	Treatment Train (Check components that apply)
	☐ Others  ☑ Good condition ☐ Needs Maintenance ☑ Sampling ports properly marked and functional ☑ Sampling/maintenance log displayed and up to date
	#Equipment properly identified  #Quantity of groundwater treated annually 3.3 million (arrange around solume)  #Quantity of surface water treated annually 1/h  Remarks Wanium the stability abidia are anguarry in 4 systems.
2.	Electrical Enclosures and Panels (properly rated and functional) □ N/A ■ Good condition□ Needs Maintenance Remarks
3.	Tanks, Vaults, Storage Vessels  □ N/A  □ Good condition□ Proper secondary containment □ Needs Maintenance Remarks
4.	Discharge Structure and Appurtenances  □ N/A  ☑ Good condition□ Needs Maintenance  Remarks
5.	Treatment Building(s) □ N/A ☑ Good condition (esp. roof and doorways) □ Needs repair ☑ Chemicals and equipment properly stored Remarks
6.	Monitoring Wells (pump and treatment remedy)  □ Properly secured/locked □ Functioning □ Routinely sampled □ Good condition □ All required wells located □ Needs Maintenance ❷N/A  Remarks
D.	Monitoring Data
1,	Monitoring Data ⊠Is routinely submitted on time ⊠Is of acceptable quality
2.	Monitoring data suggests;  □ Groundwater plume is effectively contained □ Contaminant concentrations are declining

•								
D. M	onitored Natural Attenuation							
. good r	Monitoring Wells (natural attenuation remedy)  □ Properly secured/locked □ Functioning □ Routinely sampled □ Good condition  □ All required wells located □ Needs Maintenance   Needs Maintenance   Needs Maintenance							
	X. OTHER REMEDIES							
	If there are remedies applied at the site which are not covered above, attach an inspection sheet describing the physical nature and condition of any facility associated with the remedy. An example would be soil vapor extraction.							
	XI, OVERALL OBSERVATIONS							
А.	Implementation of the Remedy							
	Describe issues and observations relating to whether the remedy is effective and functioning as designed. Begin with a brief statement of what the remedy is to accomplish (i.e., to contain contaminant plume, minimize infiltration and gas emission, etc.).  Station 6.1 J. Har for the FYR Appear.							
В.	Adequacy of O&M							
	Describe issues and observations related to the implementation and scope of O&M procedures. In particular, discuss their relationship to the current and long-term protectiveness of the remedy.  54 54 54 55 4 54 55 4 55 4 55 5 5 5 5							

C.	Early Indicators of Potential Remedy Problems
	Describe issues and observations such as unexpected changes in the cost or scope of O&M or a high frequency of unscheduled repairs, that suggest that the protectiveness of the remedy may be compromised in the future.
	Sa Sanon Lulis A This found Fin signation
D.	Opportunities for Optimization
	Describe possible opportunities for optimization in monitoring tasks or the operation of the remedy.
	Su Suniar Century of this fourth Fyr. 24211

#### Contractor to U.S. Department of Energy Office of Legacy Management

# Present Landfill- Monitoring and Maintenance Plan Inspection Form

Inspector:	Patrick Boulas	Date: 3	3/13/17 Time:	13:30	Reviewed by:	Jeremy Wehner
Temperature:	50 deg F	_Weather conditions	: Partly Cloudy			Review date: 3/27/17
Meteorological stat	tion location: Rock	y Flats Meteorologica	al Station			
			Subsidence/0	Consolidation		
Region	Evidence of cracks	Evidence of depressions	Evidence of sinkholes	Evidence of ponding		Other (Describe below)
Top cover– West	☐ Yes ⊠ No	☐ Yes ☒ No	☐ Yes ⊠ No	☐ Yes ⊠ No		
Top cover– East	☐ Yes ⊠ No	☐ Yes ☒ No	☐ Yes ⊠ No	☐ Yes ⊠ No		•
Cover side slope– North	☐ Yes ☒ No	☐ Yes ⊠ No	☐ Yes ⊠ No	☐ Yes ⊠ No		· ·
Cover side slope— South	☐ Yes ☒ No	☐ Yes ⊠ No	☐ Yes ⊠ No	☐ Yes ⊠ No		
East face slope– North	☐ Yes ⊠ No	☐ Yes ⊠ No	☐ Yes ⊠ No	☐ Yes ⊠ No		
East face slope— South	☐ Yes ⊠ No	☐ Yes ⊠ No	☐ Yes ⊠ No	☐ Yes ⊠ No		
East face slope– Central	☐ Yes ⊠ No	☐ Yes ⊠ No	☐ Yes ⊠ No	☐ Yes ⊠ No		
ast face slope– lorth Seep*	☐ Yes ☒ No	☐ Yes ⊠ No	☐ Yes ⊠ No	☐ Yes ⊠ No		
	and side slope monite rity. During year 1, thu ally thereafter.		Integrity intact 🛛 Y	es 🗌 No		
Area of seep is ou	itside of landfill cover	r and east of the cove	er anchor trench			
Vaintenance requi	red, comments, phot	o log: No maintenan	ce necessary.			
•						

LMS 6518RFS 03/08/2016

Slope Stability					
Region	Evidence of cracks	Evidence of block or circular failure	Evidence of seeps	Other (Describe below)	
Cover side slope– North	☐ Yes ⊠ No	☐ Yes ⊠ No	☐ Yes ⊠ No		
Cover side slope- South	☐ Yes ⊠ No	☐ Yes ⊠ No	☐ Yes ⊠ No		
Perimeter channel outer slope– North	☐ Yes ⊠ No	☐ Yes ⊠ No	☐ Yes ⊠ No		
Perimeter channel outer slope– South	☐ Yes ⊠ No	☐ Yes ⊠ No	Yes 🛛 No		
East face slope- North	☐ Yes ⊠ No	☐ Yes ⊠ No	☐ Yes ⊠ No	-	
East face slope– South	☐ Yes ⊠ No	☐ Yes ⊠ No	☐ Yes ⊠ No	-	
East face slope–Central	☐ Yes ⊠ No	☐ Yes ⊠ No	☐ Yes ⊠ No		
East face slope–North seep*	☐ Yes ⊠ No	☐ Yes ⊠ No	⊠ Yes □ No		
*Area of seep is outside of landfill co	over and east of the cover a	nchor trench			
Maintenance required, comments, p	hoto log: The soil was dan	np but no flow was visible ir	the east face slope - north se	еер.	

Soil Cover						
Evidence of deposition or erosion	Evidence of erosion rills or guilles	Evidence of burrowing animals	Other (Describe below)			
r–West ☐ Yes ☒ No ☐ Yes ☒ No		☐ Yes ☒ No	,			
☐ Yes ⊠ No	☐ Yes ⊠ No	☐ Yes ⊠ No				
☐ Yes ⊠ No	☐ Yes ⊠ No	☐ Yes ☒ No				
☐ Yes ☒ No	☐ Yes ☒ No	☐ Yes ☒ No	·			
☐ Yes ⊠ No	☐ Yes ⊠ No	☐ Yes ☒ No	-			
☐ Yes ☒ No	☐ Yes ⊠ No	☐ Yes ☒ No				
☐ Yes ☒ No	☐ Yes ⊠ No	☐ Yes ☒ No				
☐ Yes ⊠ No	☐ Yes ⊠ No	☐ Yes ⊠ No				
☐ Yes ⊠ No	☐ Yes ⊠ No	☐ Yes ⊠ No				
	****	Birds or insects in vent caps				
⊠ Yes □ No	⊠ Yes □ No	☐ Yes        No				
Maintenance required, comments, photo log: No maintenance necessary.						
	deposition or erosion  Yes No	Evidence of deposition or erosion       Evidence of erosion rills or guilles         ☐ Yes ☐ No       ☐ Yes ☐ No         Vent caps in place and secure       Standpipes in good condition         ☐ Yes ☐ No       ☐ Yes ☐ No	Evidence of deposition or erosion deposition or erosion       Evidence of erosion rills or guilles       Evidence of burrowing animals         □ Yes ⋈ No       □ Yes ⋈ No       □ Yes ⋈ No       □ Yes ⋈ No         □ Yes ⋈ No       □ Yes ⋈ No       □ Yes ⋈ No       □ Yes ⋈ No         □ Yes ⋈ No       □ Yes ⋈ No       □ Yes ⋈ No       □ Yes ⋈ No         □ Yes ⋈ No       □ Yes ⋈ No       □ Yes ⋈ No       □ Yes ⋈ No         □ Yes ⋈ No       □ Yes ⋈ No       □ Yes ⋈ No       □ Yes ⋈ No         □ Yes ⋈ No       □ Yes ⋈ No       □ Yes ⋈ No       □ Yes ⋈ No         Vent caps in place and secure       Standpipes in good condition       Birds or insects in vent caps         ⋈ Yes □ No       □ Yes ⋈ No       □ Yes ⋈ No			

LMS 6518RFS 03/08/2016

	Seep Treatment System					
Region	Evidence of plugging, obstructions, or excess debris	Evidence of cracks or deterioration	Other (describe below)			
GWIS inlet pipes	☐ Yes ⊠ No	☐ Yes ⊠ No				
Strip drain inlet pipe	☐ Yes ⊠ No	☐ Yes ⊠ No				
North manhole outlet pipe	☐ Yes ⊠ No	☐ Yes ⊠ No				
South manhole outlet pipe	☐ Yes ☒ No	☐ Yes ☒ No	:			
Treatment unit	☐ Yes ☒ No	☐ Yes ⊠ No				
Treatment unit outlet pipe	☐ Yes ⊠ No	☐ Yes ⊠ No				
North manhole	☐ Yes ⊠ No	☐ Yes ⊠ No				
South manhole	☐ Yes ⊠ No	☐ Yes ☒ No				
Treatment unit grating	☐ Yes ☒ No	☐ Yes ⊠ No				
Maintenance required, comments, photo log: No maintenance necessary. The new grout at the north and south manholes is in good condition.						

	Stormwater Management Structures												
Evidence of excessive settlement subsidence or gullying, scour, or undermining  Evidence of settlement subsidence or depressions		Evidence of burrowing animals		Evidence of sediment build- up or other blockage		Evidence of lining deterioration holes, rips, or separations		Evidence of lining displacement					
Diversion berm	☐ Yes	⊠ No	☐ Yes ⊠ No	☐ Yes	⊠ No	☐ Yes	⊠ No	☐ Yes	⊠ No	☐ Yes	⊠ No	☐ Yes	⊠ No
Vegetation lines perimeter channel–North	☐ Yes	⊠ No	☐ Yes ⊠ No	Yes	⊠ No	☐ Yes	⊠ No	☐ Yes	⊠ No	☐ Yes	⊠ No	☐Yes	⊠ No
Vegetation lined perimeter channel–South	☐ Yes	⊠ No	☐ Yes ⊠ No	☐ Yes	⊠ No	☐ Yes	⊠ No	☐ Yes	⊠ No	☐ Yes	⊠ No	☐ Yes	⊠ No
Riprap lined perimeter channel	☐ Yes	⊠ No	☐ Yes ⊠ No	☐ Yes	⊠ No	☐ Yes	⊠ No	☐ Yes	⊠ No	☐ Yes	⊠ No	☐ Yes	⊠ No
C350 lined east face	☐ Yes	⊠ No	☐ Yes ⊠ No	☐ Yes	⊠ No	Yes	⊠ No	☐ Yes	⊠ No	☐ Yes	⊠ No	☐ Yes	⊠ No
East face riprap channel– North	☐ Yes	⊠ No	☐ Yes ⊠ No	☐ Yes	⊠ No	☐ Yes	⊠ No	☐ Yes	⊠ No	☐ Yes	⊠ No	☐ Yes	⊠ No
East face riprap channel— South	☐ Yes	⊠ No	☐ Yes ⊠ No	☐ Yes	⊠ No	☐ Yes	⊠ No	☐ Yes	⊠ No	☐ Yes	⊠ No	☐ Yes	⊠No
Other deficiencies: N/A													
Maintenance required cor	Maintenance required, comments, photo log: No maintenance necessary.												
, and the second second	The state of the s												
			٠										

#### **Stormwater Management Structures (continued)**

#### **OUTFALLS**

Check each structure for excessive erosion and sediment depth. If sediment depth is compromising the design characteristics, remove sediment

Structure	Condition and sediment depth
Diversion Berm Outfall-North	No issue
Diversion Berm Outfall-South	No issue
Culvert 1 outfall	No issue
Culvert 2 outfall	No issue
South culvert outfall	No issue

#### **CULVERTS**

Check each structure for blockage, surrounding conditions, breaching, sediment build-up, and inlet/outlet conditions.

Structure		Condition
Culvert 1	No issue	
Culvert 2	No issue	
South Culvert	No issue	

Maintenance required, comments, photo log: No maintenance necessary.

"Run-On" Erosion Control				
Area	Adversely affecting PLF			
Run-on into perimeter channel–North	☐ Yes ☒ No Comment:			
Run-on into perimeter channel–South	☐ Yes ☒ No Comment:			
Natural drainage fed by culvert 1	☐ Yes ☑ No Comment:			
Natural drainage fed by northeast perimeter channel	☐ Yes ☑ No Comment:			
Natural drainage fed by riprap	☐ Yes ☑ No Comment:			
Maintenance required, comments, photo	log: No maintenance necessary.			


#### Contractor to U.S. Department of Energy Office of Legacy Management

Institutional Controls						
ltem						
Evidence of excavation(s) of cover and immediate vicinity of cover?	☐ Yes ☑ No Comment:					
Evidence of construction of roads, trails, on cover or buildings?	☐ Yes ☑ No Comment:					
Evidence of unauthorized entry?	☐ Yes ☒ No Comment:					
Evidence of drilling, wells or use of groundwater?	☐ Yes ⊠ No Comment:					
Disruption or damage of seep treatment system?	☐ Yes ☑ No Comment:					
Damage or removal of any signage or groundwater monitoring wells?	☐ Yes ☐ No Comment:					
Other deficiencies, photo log: N/A						


Action Items					
Deficiency	Date noted	Action	Date completed	Comments	
Vo Deficiencies	3/13/2017	:			

Inspector signature:	Date:	3/14	<u> </u>
			/

Reviewer signature:	<u> </u>	Date: 3/27/2017
---------------------	----------	-----------------







#### Attachment 1: March 2017 Monthly Report of the Original Landfill Inspection at the Rocky Flats Site

The monthly inspection of the Original Landfill (OLF) at the Rocky Flats Site, Colorado, was completed on March 22, 2017. The weather was sunny and clear during the inspection. The Rocky Flats Site Meteorological Tower recorded 0.08 inches of precipitation at the site between this inspection and the prior inspection of February 22, 2017. The National Renewable Energy Laboratory M2 tower, adjacent to the northwest corner of the site, recorded 0.30 inches during the same time period using a heated rain gauge.

Figure 1 provides the approximate locations where each of the inspection photographs were taken on the OLF (as shown in Figures 2–7).

No new signs of movement were observed on the OLF (Figure 2). No new cracks since the time of the previous inspection have been observed. Regions that show cracks that were backfilled are no longer checkmarked on the inspection form. Items that are checkmarked are from previous cracks that cannot be backfilled with hand tools. A description is included with information about the checkmarked items. The most notable cracks in 2016, southeast of Berm 5 starting just below Seep 2/3, were repaired during the September 2016 minor regrading (Figure 3), and since then, no signs of cracking or movement have been observed.

The construction of the OLF temporary groundwater intercept system started on March 14, 2017. At the time of inspection, the gravity drain line was in place and connected to the East Subsurface Drain (ESSD) (Figure 4). During the inspection, a subcontractor was flushing water through the ESSD lines and repairing the erosion control mat near the ESSD that had blown away. Weekly inspection of the ESSD and ESSD outfall has not resulted in the discovery of any visible water flowing out of the pipes; however, the ESSD outfall was damp. Erosion-control is in good condition, and most of the minor damage occurring from wildlife and high winds has been repaired (Figure 5). Staking the drainage pipe at more frequent intervals has reduced movement caused by high winds and is expected to increase the life of the drainage pipe. The revegetation of recently disturbed areas on the OLF is managed and monitored under the *Erosion Control Plan for Rocky Flats Property Central Operable Unit* (DOE 2007)<sup>1</sup> and under the sitewide vegetation and revegetation plans.

Seep 8A had the highest flow of the seeps at approximately 2 gallons per minute (gpm). Seep 2/3 was flowing less than 1 gpm and Seep 7 was damp. Seep 9 and Seep 4 had pockets of water with no visible flow. A wet area was discovered, about 30 feet north of the Seep 2/3 drainage outfall, flowing at approximately 1 gpm (Figure 6). The wet area appears to be from water in the East Perimeter Channel (EPC) that percolates through the EPC side slope instead of

<sup>&</sup>lt;sup>1</sup> DOE (U.S. Department of Energy), 2007. Erosion Control Plan for Rocky Flats Property Central Operable Unit, DOE-LM/1497-2007, Office of Legacy Management, Rocky Flats Environmental Technology Site, July.

towards the EPC outfall. This water then continues to run south along the Seep 2/3 drainage pipe, creating pockets of water and damp soil running to Woman Creek (Figure 7). The Seep 2/3 drainage pipe was moved so that the drainage outfall would discharge in the EPC, in an effort to reduce the amount of water at the wet area. The wet area will be monitored to determine the effects of moving the Seep 2/3 drainage pipe, and to observe whether it is being fed by surface or subsurface sources. No ground movement has been observed in this area since the previous inspection. The rest of the historic seep locations on the OLF were dry at the time of inspection.

#### Summary

No new ground movement of the OLF cover was observed during the inspection. Minor corrugated drainage pipe damage behind Berm 7 was repaired. A wet area was discovered that appears to shortcut the EPC outfall to Woman Creek. The inspection forms are filled out to represent current conditions at the OLF. Repaired items will no longer be checkmarked as evidence unless further action is warranted.




Figure 1. Location and Direction of Each of the Photographs Referred to in this Report (Figures 2–7), Rocky Flats Site OLF




Figure 2. Looking South at Berm 4 and the New Above-Ground Drain Pipe Running from the OLF Groundwater Intercept System to the ESSD



Figure 3. Looking West, Just East of Berm 6




Figure 4. Looking West, at Berm 4 and the Gravity Drain Line Connection to the  ${\ensuremath{\sf ESSD}}$ 



Figure 5. Standing on Berm 7 Looking North to Berm 6




Figure 6. Standing Below the Seep 2/3 Drainage Outfall Looking North at the Wet Area Discovered (estimated outline in blue)




Figure 7. Standing Above the Seep 2/3 Drainage Outfall Looking South at the Wet Area Discovered

Inspector:	Patrick Boulas	Date: <u>3/</u>	22/17 Time:	11:30 AM	Reviewed by:	Jeremy Wehner
Temperature:	56 DEG F	Weather conditions:	Sunny			Review date: 4/3/2017
			Subsidence/0	Consolidation		
Region	Evidence of cracks	Evidence of depressions	Evidence of sink holes	Evidence of ponding		Other (Describe below)
Top cover–Wes	t ☐ Yes ☒ No	☐ Yes ⊠ No	☐ Yes ⊠ No	☐ Yes ⊠ No		
Top cover– Eas	t ☐ Yes ⊠ No	☐ Yes ⊠ No	☐ Yes ⊠ No	☐ Yes ⊠ No		
Buttress fill	☐ Yes ⊠ No	☐ Yes ⊠ No	☐ Yes ☒ No	☐ Yes ⊠ No		
Diversion Berm	1 ☐ Yes ⊠ No	☐ Yes ⊠ No	☐ Yes ⊠ No	☐ Yes ⊠ No		
Diversion Berm	2 ☐ Yes ☒ No	☐ Yes ☒ No	☐ Yes ⊠ No	☐ Yes ⊠ No		
Diversion Berm	3 ☐ Yes ⊠ No	☐ Yes ⊠ No	☐ Yes ⊠ No	☐ Yes ⊠ No		
Diversion Berm	4 ☐ Yes ⊠ No	☐ Yes ⊠ No	☐ Yes ⊠ No	⊠ Yes □ No	Salt stain	
Diversion Berm	5 ☐ Yes ⊠ No	☐ Yes ⊠ No	☐ Yes ⊠ No	⊠ Yes □ No	Salt stain	
Diversion Berm	6 ☐ Yes ⊠ No	☐ Yes ⊠ No	☐ Yes ⊠ No	☐ Yes ⊠ No		
Diversion Berm	7 ☐ Yes ☒ No	☐ Yes ⊠ No	☐ Yes ⊠ No	☐ Yes ⊠ No		
Settlement plate	s—inspection integrity	. Intact ⊠ Yes ☐ No				
recorded 0.08 ir	ches of precipitation si	or photo log: No new not the last monthly reame time period using	port. The National	Renewable Energy	Laboratory M2	e Rocky Flats Site Meteorological Tower tower, adjacent to the northwest corner of th

LMS 6517RFS 03/08/2016

Slope Stability					
Region	Evidence of cracks	Evidence of seeps	Evidence of block or circular failure	Other (Describe below)	
Cover– West	☐ Yes ⊠ No	⊠ Yes □ No	☐ Yes ⊠ No		
Cover– East	☐ Yes ⊠ No	⊠ Yes □ No	☐ Yes ⊠ No		
Buttress fill side slope	☐ Yes. ⊠ No	☐ Yes ⊠ No	☐ Yes ☒ No		
West perimeter channel side slopes	⊠ Yes □ No	☐ Yes ⊠ No	☐ Yes ⊠ No		
East perimeter channel side slopes	☐ Yes ⊠ No	☐ Yes ⊠ No	☐ Yes ⊠ No	Wet area found near Seep 2/3 drainage outfall	
Cover seeps (if present)	☐ Yes ⊠ No	☐ Yes ⊠ No	☐ Yes ⊠ No		

Maintenance required, comments, and/or photo log: East Perimeter Channel (EPC) had no visible flow, but mud and pockets of water were present throughout the channel. Seep 8A had the highest flow of the seeps at approximately 2 gallons per minute (gpm). Seep 2/3 was flowing at less than 1 gpm and Seep 7 was damp. Seep 9 and Seep 4 had pockets of water but no visible flow. A wet area was discovered about 30 feet north of the Seep 2/3 drainage outfall. The source of the wet area is not clear at this time. The wet area is running south along the Seep 2/3 drainage pipe and has pockets of water and damp soil leading to Woman Creek. No ground movement has been observed in this area since the discovery of the wet area. The Seep 2/3 drainage pipe was moved to the EPC and the wet area will be monitored to determine if it is being fed by surface or subsurface sources, and any effects will be recorded.

LMS 6517RFS 03/08/2016

Soil Cover						
Region	Evidence of deposition or erosion	Evidence of erosion rills or gullies	Evidence of burrowing animals	Other (Describe below)		
Cover– West	☐ Yes ⊠ No	☐ Yes ⊠ No	☐ Yes 🛛 No			
Cover- East	☐ Yes ⊠ No	☐ Yes ⊠ No	☐ Yes ⊠ No			
Buttress fill	☐ Yes ⊠ No	☐ Yes ⊠ No	☐ Yes 🛛 No			
Buttress fill side slope	☐ Yes ⊠ No	☐ Yes ⊠ No	☐ Yes ⊠ No			
Maintenance required, c	ommonts and/or pho	to log: N/A				
Maintenance required, C	omments, and/or prio	to log. IN/A				
		•				

Vegetation					
Region	Condition of grass	Unwanted vegetation present*	Percentage of grass versus bare ground	Percentage of unwanted vegetation	
Cover– West	See Comments	☐ Yes ☐ No	·	-	
Cover- East	See Comments	☐ Yes ☐ No			
Diversion Berm 1	See Comments	☐ Yes ☐ No			
Diversion Berm 2	See Comments	☐ Yes ☐ No	· · · · · · · · · · · · · · · · · · ·		
Diversion Berm 3	See Comments	☐ Yes ☐ No			
Diversion Berm 4	See Comments	☐ Yes ☐ No			
Diversion Berm 5	See Comments	☐ Yes ☐ No			
Diversion Berm 6	See Comments	☐ Yes ☐ No			
Diversion Berm 7	See Comments	Yes No			
West perimeter channel	See Comments	☐ Yes ☐ No			
East perimeter channel	See Comments	☐ Yes ☐ No			
Upper buttress fill side slope	See Comments	☐ Yes ☐ No			
Lower buttress fill side slope	See Comments	☐ Yes ☐ No	-		
	weeds and "woody vegetation." Wer section 3.5 of the Original Landfil			int must be removed. Other	

Maintenance required, comments, and/or photo log: Vegetation inspection is no longer required by Rocky Flats Legacy Management Agreement. New areas of disturbance are addressed under the site wide revegetation plan, "Erosion Control Plan for Rocky Flats Property Central Operable Unit."

LMS 6517RFS 03/08/2016

		Stormwater Mana	agement Struc	tures			
		Chi	annels				
Evidence of excessive Structure erosion, gullying, scour, or undermining		Evidence of settlement, subsidence, or depressions	Evidence of breaching or l failure		Evidence of burrowing animals	Evidence of sediment build-up or other blockage	
Diversion Berm 1	☐ Yes ⊠ No	☐ Yes ⊠ No	☐ Yes	⊠ No	☐ Yes ⊠ No	Yes ⊠ No	
Diversion Berm 2	☐ Yes ⊠ No	☐ Yes ⊠ No	☐ Yes	⊠ No	☐ Yes ⊠ No		
Diversion Berm 3	☐ Yes ⊠ No	⊠ Yes □ No	☐ Yes	⊠ No	☐ Yes 🛛 No		
Diversion Berm 4	☐ Yes ☒ No	⊠ Yes □ No	☐ Yes	⊠ No	☐ Yes ⊠ No	Yes No	
Diversion Berm 5	☐ Yes ⊠ No	⊠ Yes □ No	☐ Yes	⊠ No	☐ Yes ⊠ No		
Diversion Berm 6	☐ Yes ⊠ No	⊠ Yes □ No	☐ Yes	⊠ No	☐ Yes ⊠ No	⊃ Yes ⊠ No	
Diversion Berm 7	☐ Yes ⊠ No	⊠ Yes □ No	☐ Yes	⊠ No	☐ Yes ⊠ No		
Temporary check dams*	☐ Yes ⊠ No	☐ Yes ⊠ No	☐ Yes	⊠ No	☐ Yes ⊠ No	Yes ⊠ No	
West perimeter channel	☐ Yes ⊠ No	☐ Yes ⊠ No	☐ Yes	⊠ No	☐ Yes ⊠ No	☐ Yes ☑ No	
East perimeter channel	☐ Yes ⊠ No	☐ Yes ⊠ No	☐ Yes	⊠ No	☐ Yes ⊠ No	⊃ Yes ⊠ No	
*Check dams may be removed a	after vegetation is estab	lished.		<del></del>		<u> </u>	
Other deficiencies: None	·		***************************************				
Maintenance required, comment	ts, and/or photo log: Th	ne damaged corrugated	drainage pipe beh	nind Ber	m 7 was repaired.		

#### **Stormwater Management Structures (continued)**

#### Outfalls

Check each structure for excessive erosion and sediment depth. If sediment depth is compromising the design characteristics, remove sediment.

Structure	Condition and sediment depth		
Diversion Berm Outfall 1	No issues		
Diversion Berm Outfall 2	No issues		
Diversion Berm Outfall 3	No issues		
Diversion Berm Outfall 4	No issues		
Diversion Berm Outfall 5	No issues		
Diversion Berm Outfall 6	No issues		
Diversion Berm Outfall 7	No issues		
West perimeter channel outfall	No issues, dry, no flow		
East perimeter channel outfall	Muddy with pockets of water, no visible flow		
French drain outfall (SID)	Dry, no flow		

Other deficiencies: None

Maintenance required, comments, and/or photo log: No new erosion or sediment buildup. There were mud and pockets of water at the EPC outfall. The East Subsurface Drain (ESSD) outfall had no flow but the ESSD outfall channel was damp in the weekly inspections leading up to the monthly inspection. At the time of the monthly inspection, the ESSD lines were being flushed with water per the subcontractor's punch list and water was observed at the outfall.

	"Run-On" Control				
Area			Adverse	ly affecting OLF	
North of the original landfill	☐ Yes ⊠ No	Comment:			
West of the west perimeter channel	☐ Yes ⊠ No	Comment:			
East of the east perimeter channel	☐ Yes ⊠ No	Comment:			
North of Woman Creek	☐ Yes ⊠ No	Comment:			
Maintenance required: N/A					
					,

#### Contractor to U.S. Department of Energy Office of Legacy Management

Institutional Controls				
ltem				
Evidence of excavation(s) of cover and immediate vicinity of cover?	☐ Yes ☒ No Comment:			
Evidence of construction of roads, trails, or buildings on cover?	☐ Yes ☒ No Comment:			
Evidence of drilling of wells or use of groundwater?	☐ Yes ☒ No Comment:			
Damage or removal of any signage or groundwater monitoring wells?	☐ Yes ☑ No Comment:			
Other deficiencies and/or photo log: The 2017 OLF Temporary Ground upgradient of the OLF cover and outside the OLF boundary.	dwater Intercept System described in CR 2017-01 has two wells that have been drilled just			

Deficiency	Date noted	Action	Date completed	Comments
Drainage pipe behind Berm 7 was damaged	3/22/17	Drainage pipe was repaired with new coupler and taped	3/22/17	· · · · · · · · · · · · · · · · · · ·
Erosion-control mat disturbed south of berm 7	3/22/17	Restaked erosion control mat, ecologist was notified	3/22/17	
-				

Inspector signature:		Date:	4/12/2017
Reviewer signature:	-A-CUL	Date:	4/12/2017